

Item P22-0001
Horizontal Tee Molds

Item	Description	Attributes
22-0001		Model: TAC-1T1T Cable Size Run: 2 SOL Cable Size Tap: 2 SOL Weld Metal Required: 45
22-0003		Model: TAC-2G2G Cable Size Run: 2/0 Cable Size Tap: 2/0 Weld Metal Required: 90
22-0038		Model: TAC-2Q2Q Cable Size Run: 4/0 Cable Size Tap: 4/0 Weld Metal Required: 150
22-0040		Model: TAC-3Q3Q Cable Size Run: 500 Cable Size Tap: 500 Weld Metal Required: (2) 150
22-0042		Model: TAC-3Q2Q Cable Size Run: 500 Cable Size Tap: 4/0 Weld Metal Required: 150

Required Tools for Horizontal Tee Molds:

Handle Clamps

Item [22-0028](#) Model: L160