



Item P13-0022
300 Power Drive With Geared Threader

Item	Description	Attributes
13-0178	Pipe Support Stand	Details: Required components for front mount applications; Models 141 & 161
13-0091	#844 Drive Bar	Details: Required components for front mount applications; Models 141 & 161
13-0089	#758 Loop (For 141 Geared Threader Applications) #346 Support Arms (For 161 Geared Threader Applications)	Details: Required components for front mount applications; Models 141 & 161
13-0087	#840A Universal Drive Shaft	Details: Required Components for Rear Mount Applications; Models 141 & 161
13-0073	#346 Support Arms	Details: For 161 Geared Threader Applications