



Item P14-4041

Quick-Lok® Mounting System

The Quick-Lok System is designed for long term hard hat and accessory use. Quick-Lok Mounting Blocks are designed to be screwed onto the hard hat. Quick-Lok Mounting Cups are designed to attach to Fibre-Metal Welding helmets, Faceshields and Welding Goggles and be securely mounted onto, and removed from the hard hat without tools.

Item	Description	Attributes
14-4041	Quick-Lok® mounting block (For attaching to hard hat)	
14-4042	Quick-Lok® mounting cup (For attaching to accessory)	